

Accessories

PLS-5219GDSK

ground disk to buss together
the six ground contacts
(solder connectors only)



PLS-5219 CBGD/ PG29

strain relief directly coupling into thread housing



M2250/1-01

crimp tool

PLS-5219CPM

crimp male contact

PLS-5219CPFE

crimp female earth contact

PLS-5219CPF

crimp femal contact

